## AIR TURQUOISE SA | PARA-TEST.COM

Route du Pré-au-Comte 8 A CH-1844 Villeneuve A +41 (0)21 965 65 65

Test laboratory for paragliders, paraglider harnesses and paraglider reserve parachutes



## Flight test report: EN 926-2:2013 & LTF 91/09

Manufacturer **Davinci Products Inc.** Certification number PG\_1237.2017 Address 53 sinchon-gil, Okcheon- Date of flight test 15. 09. 2017

myeon, Yangpyeong-gun 12505 Gyeonggi-do Republic of Korea

Glider model Duet 39 Classification B
Serial number TDT39-1708013-SBDGO Representative None
Trimmer yes: opened Place of test Villeneuve

Trimmer yes: opened Folding lines used no

Test pilot Thurnheer Claude Zoller Alain

Harness Sup' Air - Evasion Advance - Bi pro 2

Harness to risers distance (cm)4644Distance between risers (cm)5555Total weight in flight (kg)110190

_			
Smooth, easy and constant rising	Α	Easy rising, some pilot correction is required	В
No	Α	No	Α
A			
No	Α	No	Α
В			
Yes	Α	Yes	Α
Yes	Α	Yes	Α
Less than 25 km/h	Α	25 km/h to 30 km/h	В
A			
not available	0	not available	0
not available	U	not available	U
not available	0	not available	0
Increasing / greater than 65 cm	Α	Increasing / greater than 65 cm	Α
0			
not available	0	not available	0
not available	0	not available	0
0			
not available	0	not available	0
A			
Reducing	Α	Reducing	Α
A			
Spontaneous exit	Α	Spontaneous exit	Α
A			
Immediate reduction of rate of turn	Α	Immediate reduction of rate of turn	Α
	No A No B Yes Yes Yes Less than 25 km/h A not available not available Increasing / greater than 65 cm 0 not available not available o not available A Reducing A Spontaneous exit A Immediate reduction of rate of	Smooth, easy and constant rising A  No A A No A B Yes A Yes A Less than 25 km/h A A  not available 0  not available 0 not available 0 not available 0 not available 0  Reducing A Spontaneous exit A Immediate reduction of rate of A	Smooth, easy and constant rising A Easy rising, some pilot correction is required  No A No  A No  B Yes A Yes Yes A Yes Less than 25 km/h A 25 km/h to 30 km/h  A  not available 0 not available  Increasing / greater than 65 cm A Increasing / greater than 65 cm  O not available 0 not available  Increasing / greater than 65 cm A Increasing / greater than 65 cm  O not available 0 not available  O not available 0 not available  O not available 0 not available  A Reducing A Reducing  A Spontaneous exit A Immediate reduction of rate of turn

Tendency to return to straight flight	Spontaneous exit (g force decreasing, rate of turn decreasing)	Α	Spontaneous exit (g force decreasing, rate of turn decreasing)	Α
Turn angle to recover normal flight	Less than 720°, spontaneous recovery	Α	Less than 720°, spontaneous recovery	Α
10. Symmetric front collapse	A			
Approximately 30 % chord				
Entry	Rocking back less than 45°	Α	Rocking back less than 45°	Α
Recovery	Spontaneous in less than 3 s	Α	Spontaneous in less than 3 s	Α
•	•		•	
Dive forward angle on exit Change of course	Dive forward 0° to 30° Keeping course	Α	Dive forward 0° to 30° Keeping course	Α
Cascade occurs	No	Α	No	Α
Folding lines used	No		No	
At least 50% chord				
Entry	Rocking back less than 45°	Α	Rocking back less than 45°	Α
Recovery	Spontaneous in less than 3 s	Α	Spontaneous in less than 3 s	Α
Dive forward angle on exit / Change of course	Dive forward 0° to 30° / Keeping	Α	Dive forward 0° to 30° / Keeping	Α
Dive forward drigite on exit? Onlying of course	course		course	٨
Cascade occurs	No	Α	No	Α
Folding lines used	No		No	
With accelerator				
Entry	not available	0	not available	0
Recovery	not available	0	not available	0
Dive forward angle on exit / Change of course	not available	0	not available	0
Cascade occurs	not available	0	not available	0
Folding lines used	Not available	Ū	Not available	Ü
11. Exiting deep stall (parachutal stall)	A		Not available	
Deep stall achieved	Yes	Α	Yes	Α
Recovery	Spontaneous in less than 3 s	Α	Spontaneous in less than 3 s	Α
			Dive forward 0° to 30°	
Dive forward angle on exit	Dive forward 0° to 30°	A		A
Change of course	Changing course less than 45°	A	Changing course less than 45°	A
Cascade occurs	No	Α	No	Α
12. High angle of attack recovery	A		and accellable	0
Recovery	Spontaneous in less than 3 s	A	not available	0
Cascade occurs	No	Α	not available	0
13. Recovery from a developed full stall	B		D	_
Dive forward angle on exit	Dive forward 0° to 30°	Α	Dive forward 30° to 60°	В
Collapse	No collapse	Α	No collapse	Α
Cascade occurs (other than collapses)	No	Α	No	Α
Rocking back	Less than 45°	Α	Less than 45°	Α
Line tension	Most lines tight	Α	Most lines tight	Α
14. Asymmetric collapse	В			
Small asymmetric collapse				
Change of course until re-inflation / Maximum dive forward or roll angle	Less than 90° / Dive or roll angle 0° to 15°	Α	Less than 90° / Dive or roll angle 15° to 45°	Α
Re-inflation behaviour	Spontaneous re-inflation	Α	Spontaneous re-inflation	Α
Total change of course	Less than 360°	Α	Less than 360°	Α
Collapse on the opposite side occurs	No (or only a small number of	Α	No (or only a small number of	Α
Collapse of the opposite side occurs	collapsed cells with a spontaneous reinflation)	^	collapsed cells with a spontaneous reinflation)	^
Twist occurs	No	Α	No	Α
Cascade occurs	No	Α	No	Α
Folding lines used	No		No	
Large asymmetric collapse				
Change of course until re-inflation / Maximum dive forward or	90° to 180° / Dive or roll angle	В	90° to 180° / Dive or roll angle 15°	В
roll angle	15° to 45°	ر	to 45°	ی

Re-inflation behaviour	Spontaneous re-inflation	Α	Spontaneous re-inflation	Α
Total change of course	Less than 360°	Α	Less than 360°	Α
Collapse on the opposite side occurs	No (or only a small number of collapsed cells with a spontaneous reinflation)	Α	No (or only a small number of collapsed cells with a spontaneous reinflation)	Α
Twist occurs	No	Α	No	Α
Cascade occurs	No	Α	No	Α
Folding lines used	No		No	
Small asymmetric collapse with fully activated accelerator				
Change of course until re-inflation / Maximum dive forward or roll angle	not available	0	not available	0
Re-inflation behaviour	not available	0	not available	0
Total change of course	not available	0	not available	0
Collapse on the opposite side occurs	not available	0	not available	0
Twist occurs	not available	0	not available	0
Cascade occurs	not available	0	not available	0
Folding lines used	Not available		Not available	
Large asymmetric collapse with fully activated accelerator				
Change of course until re-inflation / Maximum dive forward or roll angle	not available	0	not available	0
Re-inflation behaviour	not available	0	not available	0
Total change of course	not available	0	not available	0
Collapse on the opposite side occurs	not available	0	not available	0
Twist occurs	not available	0	not available	0
Cascade occurs	not available	0	not available	0
Folding lines used	Not available		Not available	
15. Directional control with a maintained asymmetric	A			
collapse				
Able to keep course	Yes	Α	Yes	Α
180° turn away from the collapsed side possible in 10 s	Yes	Α	Yes	Α
Amount of control range between turn and stall or spin	More than 50 % of the symmetric control travel	Α	More than 50 % of the symmetric control travel	Α
16. Trim speed spin tendency	A			
Spin occurs	No	Α	No	Α
17. Low speed spin tendency	Α			
Spin occurs	No	Α	No	Α
18. Recovery from a developed spin	Α			
Spin rotation angle after release	Stops spinning in less than 90°	Α	Stops spinning in less than 90°	Α
Cascade occurs	No	Α	No	Α
19. B-line stall	Α			
Change of course before release	Changing course less than 45°	Α	Changing course less than 45°	Α
Behaviour before release	Remains stable with straight span	Α	Remains stable with straight span	Α
Recovery	Spontaneous in less than 3 s	Α	Spontaneous in less than 3 s	Α
Dive forward angle on exit	Dive forward 0° to 30°	Α	Dive forward 0° to 30°	Α
Cascade occurs	No	Α	No	Α
20. Big ears	Α			
Entry procedure	Dedicated controls	Α	Dedicated controls	Α
Behaviour during big ears	Stable flight	Α	Stable flight	Α
Recovery	Spontaneous in less than 3 s	Α	Spontaneous in less than 3 s	Α
Dive forward angle on exit	Dive forward 0° to 30°	Α	Dive forward 0° to 30°	Α
21. Big ears in accelerated flight	0			
Entry procedure	not available	0	not available	0
Behaviour during big ears	not available	0	not available	0
Recovery	not available	0	not available	0
Dive forward angle on exit	not available	0	not available	0
Behaviour immediately after releasing the accelerator while	not available	0	not available	0
maintaining big ears				

22. Alternative means of directional control	Α		
180° turn achievable in 20 s	Yes	A Yes	Α
Stall or spin occurs	No	A No	Α
23. Any other flight procedure and/or configuration described in the user's manual	0		
Procedure works as described	not available	0 not available	0
Procedure suitable for novice pilots	not available	0 not available	0
Cascade occurs	not available	0 not available	0

24. Comments of test pilot

Comments